

ECS SEPARATOR SERVICING

Despite the widespread installation of oil separators (interceptors) in areas of contaminated run-off risk, water courses are still becoming polluted and site owners prosecuted. This can often be attributed to lack of maintenance, faulty parts and on some occasions incorrect installation.

Our operatives will ensure that your pollution prevention measures are working at peak levels of performance keeping the environment clean, and the regulators satisfied.

COMMISSIONING

The entire installation will be checked in detail and, if all the manufacturer's instructions have been adhered to, a certificate can be issued to facilitate formal site handover.

SERVICE

Regular servicing will keep all pollution prevention equipment working at optimum efficiency levels whilst satisfying the need for service log scrutiny during environmental inspections. ECS Limited offer 1 to 5-year service contracts.

ALARM INSTALLATION

A correctly fitted alarm will reduce the waste management costs of unnecessary emptying whilst ensuring that overflow is avoided. It is important to remember that this equipment needs to be maintained/serviced.

AUDITS

ECS Limited will carry out a full site audit on existing separators to identify any issues or potential problems, prior to establishing a service agreement.

STRUCTURAL SURVEY

A full tank Structural Survey should be carried out every five years under pollution prevention guidelines. ECS engineers will carry out a thorough inspection of your installation and help resolve any issues identified.



**WE CAN ALSO QUOTE
FOR INSTALLATION**

(upon request - certain parts of UK mainland only)



ENVIRONMENTAL CONSTRUCTION SOLUTIONS LIMITED

Tel. 08456 123 332

Fax. 08456 123 334

www.ecs-sales.co.uk